

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19

BEST AVAILABLE COPY





FIG. 20



2540


FIG. 21

2520

Terminal Status | Modules | Version Info | Configuration | Metrics | Self Tests | Status Log | Service Calls | Service Docs

Status & Tests | Service Calls | Status Log | Version Info | Configuration | Metrics | Service Docs | Firmware Download

Advanced Function Dispenser (1): Supplies Warning



Toggle Show
Ok Statuses

Module Tests and Commands:

- Reset Test
- Self Test
- Sensor State Test
- Firmware Download**
- Lead through Test
- Set AFD Communication
- Get Cassette Information
- Calibrate
- Generate Engineering Data(DAQ) Test
- Diverter Test
- Exit Shutter Test
- Last Asset Test
- Motor Test
- Push Plate Test
- Transport Test
- Tray Test

Run Test

View 1 of 1 << >>

Component	Status
Divert/Retract Cassette or Bin	0x0001
Status	No cassette
USB result	Ok
Security result	Ok
Module	All module functions available
CCA board	0x0000
Status	Ok
Distance measurement	Ok
Recovery Action (Divert/Retract Cassette or Bin Status: No cassette)	
25	Verify divert/reject cassette or bin is present and fully inserted
20	Rescan CCA Cable connector in I2C stacker sensor harness

2530

2570

2510

2600

2620

2610

FIG. 22

BEST AVAILABLE COPY




FIG. 23

Diebold Diagnostics

Terminal Status

Modules

Version Info

Configuration

Metrics

Self Tests

Status Log

Service Calls

Service Docs

Status & Tests

Service Calls

Status Log

Version Info

Configuration

Metrics

Service Docs

Address: 10.Ytechpua2BOOKS7M-100001-001V1b10-10001-001-1.Hmd/5173001

Go

Back


Forward

Home

4.1.2 Replacement

To replace the fascia plate, reverse the removal procedure.
Grease the gate with Diebold lubricant (PN 16-003082-000A) before

Figure 4-1 Removing the Lead-through Indicator and Exit






FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 32




FIG. 33